

LTB00782V4



TECHNICAL BULLETIN

28 OCT 2015

© Jaguar Land Rover Limited

All rights reserved.

INFORMATION

SITUATION:

This bulletin supersedes TSB LTB00782v3/2015 dated 01 OCT 2015, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

307-00

SUBJECT/CONCERN:

Automatic Transmission Shift Concerns

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Range Rover Evoque (LV)	2012-2013	600000-856580	Halewood	Vehicles With: AWF21 6-Speed Automatic Transmission